

Dart Aerospace Ltd. 1270 Aberdeen St Hawkesbury, ON K6A 1K7 Canada

ENGINEERING CHANGE REQUEST

Tel (613) 632-5200 Fax 613 632-5246

ECR 158 2/12/21 4:12 PM Date Opened: Requested By: Becker, Jacob Type: Drawing/Pattern Change Responsible Engineer: Fuentes, Roberto Priority: High Requester*: Duval, David Status: **Under Review** ECR Lead*: Drouin, Steven Reason: Adjust mounting holes on the 646.9710 cutter DE Approver*: Gardiner, Jason body to match the mounting rail spacing 647.2110 ECR Lead*: Becker, Jacob or 647.2113 Expense: **Target Date: Execution Date: ECR Approval No:** RE (R&D): **BRIEF 646,9700 J, dimensional issue, CCK (Various) **DESCRIPTION**:** Status Note: **DESCRIPTION/ ADR** 646.9710 Cutter body does not align with the CONTENT**: Mounting rail 647.2110 or 647.2113. **CUSTOMER APPROVALS Customer Visible Customer Approval Required** Customer **Customer Approved PARTS Part No Part Status Customer Part Special Comments Documents** Rev Name Type 646.9710 On hold Body Sub-assembly **INVENTORY DISPOSITION Part No Revision Material No Current Inventory Qty Purchasing On-Order Qty Qty Scheduled for Production** 646.9710 15 Quarantine 0 0 **EFFECTS Effect Group Effects** Immediate quarantine required 1. Quarantine? 2. ECR Lead Assessment - Impacted Docs & Output Drawing Change Required (646.9700) 3. ECR Lead Assessment - Status During ECR UR - Full Under Review 4. Production Type In-house production 5A. ECR Lead Assessment - MINOR Changes Correction of drawing errors, Minor change to component to improve fit or manufa